Cu

Shes

FIELD INSPECTION REPORT

Date of	Inspection:	11-12-20	District: Rohly	
Division: Saderun-1			Length (km): 2.20	
Name of	The second secon	UD Road Kar	rayi mill to Hew Had.	
Scheme	Programme:	MAINTENANCE		
Package	No.:		Road Id No.:	
Status o	f the Project:		ed/Under Maintenance	
Work is	a case of:	New Connectivity	/Up gradation/ Maintenance	
SI. No.	Parameters to be checked		Remarks	
1.	Pavement			
a)	Road Junction condition			S/U
b)	Pavement Road Junction condition Condition of Surfacing			S/U
c)	Riding Quality Road Camber			S/U
d)	Road Camber No			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drainage			20
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			1
a)	Status of ATR's & any others			
				-

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Jul 11:13:00

(Signature)

NAME:

DESIGNATION: