FIELD INSPECTION REPORT

Date of	Inspection:	12-12-20	District: foh tos	
Division: Lasgram-L			Length (km): S-SO	
Name o	fthe Road: A	ampur Bazi	or to Pangrighat	
	/Programme:	MAINTENANCE		
Package		To 1 10 1	Road Id No.:	
	f the Project:		ted/Under Maintenance y/Up gradation/ Maintenance	
SI. No.	Control of the Contro			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			SAU
d)	Road Camber			SIU
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavernent)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drains	ge		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			\$/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.85	Compliance History			
a)	Status of ATR's & any others			No.

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

12.12. E

:

(Signature)

NAME:

DESIGNATION:

W