

FIELD INSPECTION REPORT

Date of Inspection: 12.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 2.110 km
Name of Road: To 5 to mahisheshi rikas pur		
Scheme / Programme: MAINTENANCE		MR old,
Package No:		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	Compliance History	
a)	Status of ATR's & any others	

Work progress is not as per milestone.
Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	

12/12/20
(Signature)

NAME: Anil Prasad
DESIGNATION: JTO