

FIELD INSPECTION REPORT

Date of Inspection :	25.12.2024	District :	Wardha
Division :	Roads, Buxar	Length (km) :	8.50 Km
Name of the Road :	Nandi Bazar Bypass Road, Road No. 141/142		
Scheme/Programme :	MAINTENANCE		
Package No. :		Road Id No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/O	
b)	Condition of Surfacing	S/O	
c)	Riding Quality	S/O	
d)	Road Camber	S/O	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ☒ NA	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ☒ NA	
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒ NA	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/O ☒ NA	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/O ☒ NA	
c)	Condition of railings/slab/approach for Bridges	S/SR/O ☒ NA	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	☒ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

3.12.2020
J.D

[Signature]
03/12/23
(Signature) AE