

FIELD INSPECTION REPORT

Date of Inspection : 2.12.20	District: Madhepura
Division : Uda Kiangam	Length (km): - 3.56 Km
Name of the Road: M/R of Rd from Bihangam to Sakaraha	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 1592846
Status of the Project: <input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No In Progress.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No <input checked="" type="checkbox"/>
4.	Compliance History	
a)	Status of ATR's & any others	No


Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


Work in initial stage

Road junction & slope

NAME:


 (Signature)
 J.E. Bihangam

M/R OF BIHARIGANJTO SAKARDINA RD



पथ का नाम: - MIR OF BIHARIGANJ TO SAKARDINA RD

