


FIELD INSPECTION REPORT

Date of Inspection: 12.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 4.100 km
Name of Road : To S to Rampur Samthun Samthun		
Scheme / Programme: MAINTENANCE		New M/R 2018
Package No:		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	—
b)	Condition of Surfacing	—
c)	Riding Quality	—
d)	Road Camber	—
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	—
f)	Constraction Joint provided or not(CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	—
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridge	—
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	main board fixed
4	Compliance History	
a)	Status of ATR's & any others	NO

Stipulated date of Completion is 19.11.2020 but till now BT surface work not started.

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	


 12.12.2020
 (Signature)

NAME:

DESIGNATION :

Amil prasad
 JE