

New MR

FIELD INSPECTION REPORT

Date of Inspection :	05/12/2020	District:	Bhagalpur
Division :	Kahelgaon	Length (km):	
Name of the Road:	Kanyha Ghatigani to Chandika Asthan		
Scheme/Programme:	MAINTENANCE	New maintenance policy	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <u>Ongoing</u>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance <u>Maintenance</u>		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	SU	NA
b)	Condition of Surfacing	SU	NA
c)	Riding Quality	SU	NA
d)	Road Camber	SU	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	NA
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	No
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Work just start. But Main board is not find

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME: