FIELD INSPECTION REPORT

| Date of 1 | Inspection: / | 0-12.2020 | District: Darblanga. | | |
|--|--|---------------|----------------------|---------|--|
| Division: Darbhenga-2 Length (km): 2760 K Name of the Road: Tob Nehra to Jajdish phr. | | | | , | |
| | | 36 Nehrati | o Jagdish pm. | | |
| | Programme: | MAINTENANCE | Road Id No.: | | |
| Package No.: Status of the Project: Ongoing/Completed/ | | | | | |
| | a case of: | | | MGSY) | |
| SI. No. | a case on | Parameters to | | Remarks | |
| 1. | Payement | | 100 | | |
| a) | Road Junction condition | | | S/U | |
| b) | Condition of Surfacing | | | S/U | |
| c) | Riding Quality | | | S/U | |
| d) | Road Camber | | | S/U | |
| c) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) | | | Yes/No | |
| g) | Compaction of flank/slope & raincuts if any | | | Yes/No | |
| 2. | Cross Drainage | | | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | | | S/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | | S/SRI/U | |
| c) | Condition of railings/slab/approach for Bridges | | | S/SRI/U | |
| 3. | Road Furniture | | | | |
| a) | Whether sign boards/informatory/eautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | Yes/No | |
| 4. | Compliance History | | | | |
| a) | Status of ATR's & any others | | | NO. | |

Overall Rating

| V | |
|---|---|
| Satisfactory (S) | S |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

NAME: Syer share per Alien of 15th (Signature)

DESIGNATION: ASSI Engine.