

FIELD INSPECTION REPORT

Date of Inspection : 10-12-2020	District: Darbhanga.
Division : Darbhanga-2	Length (km): 1.715
Name of the Road: Bishampur to Goriari	
Scheme/Programme:	MAINTENANCE ✓
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ✓
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓ (PMGSY)

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓ N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓ N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓ N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Syed Shauque Ahmed
DESIGNATION: Asst. Engineer.

10.12.2020
J-E
(Signature)