FIELD INSPECTION REPORT

pection: 08-12-2020 District: West cham	
Narkanggany Length (km):	-
c Rond:	
ogramme: MAINTENANCE	
Would Id IAO:	
case of: New Connectivity/Up gradation/ Maintenance	thyear
Parameters to be checked	Remarks
Davament	
Road Junction condition	S
Condition of Surfacing	5
Riding Quality	S
Road Camber	S
Whether free from defects such as visible cracks, expos	ied
	-
Compaction of flank/slope & raincuts if any	NO
Cross Drainage	1
Condition of head walls in Hume pipe culverts including its paint	ting SRI
Condition of Abutment & Wing walls, Slab in RCC culverts	SRI
ondition of railings/slab/approach for Bridges	· SRI
oad Furniture	-
hether sign boards/informatory/cautionary Board/km & 2 ones/Pavement road markings are provided and maintained	.00m NO
mpliance History	
itus of ATR's & any others	
	Parameters to be chiecked ase of: New Connectivity/Up gradation/ Maintonance Parameters to be chiecked average Condition of Surfacing Road Camber Whether free from defects such as visible cracks, exposing regates in case of CC Pavement. Contraction Joints provided or not (CC Pavement) Compaction of flank/slope & raincuts if any Condition of head walls in Hume pipe culverts including its paint condition of railings/slab/approach for Bridges Condition of railings/slab/approach for Bridges

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME: RAM HARAYAN SHAA

DESIGNATION: A.E.