FIELD INSPECTION REPORT

Date of Inspection: /4-12-2020			District: West Champeren		
Division: Bapake-2			Length (km): 1.70		
Name of	the Road:		Make tols piprating		
Scheme/	Programme:	MAINTENANCE			
Package No.: BR-37R-562			Road Id No.:		
			ed/Under Maintenance Under maintenance		
Work is	a case of:	New Connectivity	/Up gradation/ Maintenance main	tenque	
SI. No.		Parameters	to be checked	Remarks	
1.	Payament				
a) ·	Road Junction condition			چ.	
b)	Condition of Surfacing			5	
c)	Riding Quality			٠. ک	
d)	Road Camber			S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
(1)	Contraction Joints provided or not (CC Pavement)				
(g)	Compaction of flank/slope & raincuts if any				
	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				
c)	Condition of railings/slab/approach for Bridges				
3.	Road Furn	irure	And the second second	11 11	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
1	Compliane	e History		10.34.	
a) ·	Status of A	TR's & any others	y b	1	
-	4				

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Nogendres would

DESIGNATION: JE