

FIELD INSPECTION REPORT

| | |
|---|--|
| Date of Inspection : 12.12.2020 | District: Yamun |
| Division : W. Division Yamun | Length (km): |
| Name of the Road: Chaudaha Sikondra Made road to chaudaha | |
| Scheme/Programme: | MAINTENANCE |
| Package No.: | Road Id No.: 20804100321 |
| Status of the Project: | Ongoing/Completed/Under Maintenance |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance |

pokhar via
Bijragbali
Village

| Sl. No. | Parameters to be checked | Remarks |
|---------|--|-----------|
| 1. | Pavement | |
| a) | Road Junction condition | ✓S/U |
| b) | Condition of Surfacing | S/U ✓ |
| c) | Riding Quality | S/U ✓ |
| d) | Road Camber | ✓S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No ✓ |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No ✓ |
| g) | Compaction of flank/slope & raincuts if any | Yes/No ✓ |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | ✓S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U ✓ |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓ |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | |

Overall Rating :

| | |
|---|---|
| Satisfactory (S) | |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | U |

NAME: - Arjun Kumar

DESIGNATION: A.E

Arjun Kumar
12/12/2020

Arjun Kumar
12/12/20
(Signature)