

FIELD INSPECTION REPORT

Date of Inspection :	09-12-2020	District:	West Champaran
Division :	Bagaha-2	Length (km):	11.687
Name of the Road:	Khairatola Naxalwan Bridge to semtan road		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-37R-066	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	SRL
c)	Riding Quality	SRL
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SRL
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SRL
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	SRL
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRL
Unsatisfactory (U)	

Signature
05/11/20
(Signature)

NAME:

Aligendra Kumar

DESIGNATION:

JE