

# FIELD INSPECTION REPORT

Date of Inspection : 12.12.2020		District: W. Champaran	
Division : Belthorah		Length (km): 1.0 Km	
Name of the Road: Yogendra Singh's House to Bazar to 1			
Scheme/Programme:		MAINTENANCE	
Package No.: 975HY		Road Id No.: 1.0 Km	
Status of the Project:		Ongoing/Completed/Under Maintenance UNDER Maint.	
Work is a case of:		New Connectivity/Up gradation/ Maintenance New Connectivity	
Sr. No.	Parameters to be checked		Remarks
1.	<b>Pavement</b>		
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No NO
f)	Contraction Joints provided or not (CC Pavement)		Yes/No YES
g)	Compaction of flank/slope & raincuts if any		Yes/No NO
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A	S/SRI/U
3.	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No NO
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others		YES

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

*Am*  
12/12/20  
(Signature)

NAME: SUNIL KUMAR

DESIGNATION: J-E