

# FIELD INSPECTION REPORT

Date of Inspection : 12.12.2020		District: N. Chhargan
Division : Bhatnagar		Length (km): 3.0 km
Name of the Road: Parsa Hange Harnon doly & Parsa Hange Bhatnagar		
Scheme/Programme: MAINTENANCE		
Package No.: 85547	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance Completed	
Work is a case of:	New Connectivity/Up gradation/ Maintenance New Connectivity	
Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Am  
12/12/20  
(Signature)

NAME: SUNIL KUMAR

DESIGNATION: J-E