

FIELD INSPECTION REPORT

Date of Inspection : 12.12.2020	District: H. Changanacherry	
Division: Betteah	Length (km): 1.30 km	
Name of the Road: Dilep Jakanill House to Huzamdu		
Scheme/Programme:	MAINTENANCE	
Package No.: 973 NY	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance UNDER MAINT.	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/S/U
b)	Condition of Surfacing	S/S/U
c)	Riding Quality	S/S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	15
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


12/12/20
(Signature)

NAME: SUNIL KUMAR

DESIGNATION: J.E