

FIELD INSPECTION REPORT

Date of Inspection : 12.12.2020	District: N. Champaran	
Division : Bellegah	Length (km): 0.40 km	
Name of the Road: P.N. 951 Road to Koini-dol		
Scheme/Programme: MAINTENANCE		
Package No.: NH 551	Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance	Completed	
Work is a case of:	New Connectivity/Up gradation/ Maintenance New Connectivity	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S L-S/U
b)	Condition of Surfacing	S L-S/U
c)	Riding Quality	S L-S/U
d)	Road Camber	S L-S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes L-Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes L-Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes L-Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	L-S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	L-S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A L-S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	L-Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
12/12/20
(Signature)

NAME: SUNIL KUMAR
DESIGNATION: JE