

FIELD INSPECTION REPORT

Date of Inspection: 14.12.2020	District: Samastipur	
Division: RWD Dalsinghsarai	Length(km): 2.558km	
Name of Road: PWD Road to Chandauli Chapra Sarai.		
Scheme / Programme: MAINTENANCE New MP 2018		
Package No:	Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance - ongoing		
Work is a case of: New Connectivity/ Up gradation/ Maintenance - up gradation		
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	Compliance History	
a)	Status of ATR's & any others	NO

Stipulated date of completion is 19.11.2020 but till now BT surface work has not started.

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	

14/12/2020
(Signature)

NAME:

DESIGNATION :

Anil Kumar
DB