

# FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020	District: Jamui
Division : Jamui	Length (km): 1.05 Km
Name of the Road: Jamui Khasgaur PWD Road To Patana (Missing Link)	
Scheme/Programme:	MAINTENANCE
Package No.: MR-N/19-20/Jamui-1	Road Id No.: 20804102027
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	SAU N/A
b)	Condition of Surfacing	SAU N/A
c)	Riding Quality	SAU N/A
d)	Road Camber	SAU N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work not started ~

*(Signature)*  
07/12/2020

(Signature)

NAME:

(Ashok Kumar Bysa)

DESIGNATION:

AE, RWD, Laxmipura