


FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020	District: BARKA
Division: BARKA-2	Length (km): 1.438 KM
Name of the Road: Old Danka Road to Bhandarpur	
Scheme Programme: MAINTENANCE	
Package No.: RM/BA/BAN/20/0006	Road Id No.: 20703502062
Status of the Project: ☒ Ongoing/Completed/Under Maintenance	
Work is a case of: ☒ New Connectivity/Up gradation/ Maintenance	

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U Ongoing
b)	Condition of Surfacing	S/U Ongoing
c)	Riding Quality	S/U Ongoing
d)	Road Camber	S/U Ongoing
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No Ongoing
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U Ongoing
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Ongoing
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


(Signature)

NAME: RAMECH KUMAR

DESIGNATION: JE