

FIELD INSPECTION REPORT

Date of Inspection: 02/12/2020	District: Baux
Division: Baux-2	Length (km): 3.192 km
Name of the Road: Simrahon Minakola Road to Piliu	
Scheme/Programme: MAINTENANCE	
Package No: RM/BA/BAN/20/0004	Road Id No: 20703502/26
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U 'S'
b)	Condition of Surfacing	S/U On going
c)	riding Quality	S/U On going
d)	Road Camber	S/U On going
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No On going
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U On going
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No On going
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	Satisfactory 'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: RAMESH KUMAR

DESIGNATION: JE