Date of Inspection: 12/12/ 2020			District: Banka	
Division: Banka-9.			Length (km):	
	the Road:	Bhaljeri PIN	& road Dam Rd via Saupa	lahax(I
cheme/ ackage	***	MAINTENANC		
207	f the Project:	Ongoing/Compl	Road Id No.: 2070 360 80 eted/Under Maintenance	142
	a case of:		ty/Up gradation/ Maintenance	
Sl. No.				Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

NAME: Krishnow Der. Senta.

DESIGNATION: Executive Engineer
R.W. Bereka- 9.