FIELD INSPECTION REPORT

Date of Inspection: 89.12.2020			District: Jami	
Thorita			Length (km): 1.3	
Name of t	he Road: Om	at of pec loved L	st KM of William termin t	END Ed.
Scheme/P	rogramme:	MAINTENANCE	OLD MR	
Package No.:			Road Id No.: 20804208027	
Status of the Project: Ongoing/Completed		Ongoing/Completed		rounteneur
Work is		New Connectivity/U	Jp gradation/ Maintenance	AND THE PROPERTY OF THE PARTY O
SI No.	P.M. Warren	Parameters to	be checked	Remarks
	Pavement			推出数数
a)	Road Junction condition			S/U ~
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Gross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
· b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			学科学院等
a) -	Status of ATR's & any others			

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

cond of good and cour is out of maintenue

(Signature)

NAME: Anisur Rochuran

DESIGNATION: E.E.