

FIELD INSPECTION REPORT

Date of Inspection :- 7.12.20	District :- Khajuraho
Division :- Khajuraho	Length (Km) :- 0.770
Name of Road :- M/R to road from the house of Gaurish Singh to Bachhoutha Timmuhani Bhada, north parichayak	
Scheme/Programme :- M.R. old.	Maintenance
Package No. :-	Road ID No. :-
Status of Project :-	Ongoing/Complete/Under Maintenance
Work is a case of :-	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	S/U
b)	Condition of Surface	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	N.A.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note - out of 5th year maintenance

(Signature)

[Signature]
7.12.20
J.F./Khajuraho