## FIELD INSPECTION REPORT

Division	Inspection:	197/2/20 District: As an'C	
	f the Road:	And Length (km):	
	Programme:	ND ROAD KALIYA GANJ TO BY	TLUA
Package			01
Status o	f the Project:	Ongoing/Completed/Under Maintenance	91
Work is	a case of:	New Connectivity/Up gradation/ Maintenance	
SL No.		Parameters to be checked	Remark
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from detects such as visible cracks, exposed aggregates in case of CC Pavement.		S/U Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
6)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4	Compliance History		
a)	Status of ATR's	& any others	18/7/

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

out of muintenance Fulchurs 1200 dk

(Signature)