

The road does not exist in Barhaha Block.

dm
14/12/20
24

FIELD INSPECTION REPORT

Date of Inspection:

District:

Division:

Length (km):

Name of the Road: Barhaha Jango Path se Bhopatpur vilhayaak Indrakoo
Ishtad Ke ghar Tak.

Scheme/Programme: MAINTENANCE

Package No.:

Road Id No.:

Status of the Project: Ongoing/Completed Under Maintenance

Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects (such as visible cracks, exposed aggregates in case of CC Pavement)	Yes/No
f)	Construction joints (provide for no lift) - If any	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)

NAME: