

## FIELD INSPECTION REPORT

Date of Inspection : 6/12/2020		District: MUZAFFARPUR	
Division : MUZAFFARPUR WEST		Length (km): 1.5	
Name of the Road: DAMELAPUR TO SISWAN			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance (MDA/PUR)	
Sl. No.	Parameters to be checked	Remarks	
<b>1. Pavement</b>			
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
<b>2. Cross Drainage</b>			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
<b>3. Road Furniture</b>			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
<b>4. Compliance History</b>			
a)	Status of ATR's & any others	—	

Overall Rating :

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

*S. S. S. S.*  
(Signature) SF

NAME:

DESIGNATION: