


FIELD INSPECTION REPORT

Date of Inspection:- 8.12.2020		District:- Sitamarhi. Sheohar
Division:- RWD, Works Div. Pupri. Sheohar		Length (km):- 8.780 KM.
Name of the Road:- Dhankot to Minapur Fatchpur to Kauriya Lalgaon		
Scheme/Programme:- MAINTENANCE		
Package No.:-		Road Id No.: 346081080789
Status of the Project:	Ongoing/Completed/Under Maintenance N.A.	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition Old M/R without	S/U
b)	Condition of Surfacing Maintenance	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutments & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railing/slab/approach for bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 (Signature) 8.12.2020

Name:- Sudhir Kumar

DESIGNATION:- A. E.