FIELD INSPECTION REPORT Date of Inspection : 08-12-20 District : East Champaran Division : Chakia Length (Km): 3.57 Name of the Road: Pibra Kothi to Senva. Scheme/Programme: MAINTENANCE Package No.: Road ID No .: Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of : New Connectivity/Up Gradation/ Maintenance SI. No. Parameters to be checked Remarks 1. Pavement a) - NA -Road Junction condition b) - NA-Condition of Surfacing c) - NA -Riding Quality - NAd) Road Camber Whether free from defects such as visible cracks, exposed aggregates in - NAe) case of CC Pavement. f) Contraction Joints provided or not (CC Pavement) Compaction of flank/slope & raincuts if any g) Cross Drainage 2. - NA-Condition of head walls in Hume pipe culverts including its painting a) Condition of Abutment & Wing walls, Slab in RCC Culverts b) Condition of railings/slab/approach for Bridges c) Road Furniture 3. Whether sign board/informatory/cautionary Board/Km & 200m -NA-Stones/Pavement road markings are provided and maintained a) Compliance History 4, Status of ATR's & any others a)

Overall Rating :

Satisfactory (S)

Satisfactory but requires improvement (SRI)

Unsatisfactory (U)

This Road is under PMUST phase-II (DRRP)

(Signature)

NAME:

DESIGNATION: