FIELD INSPECTION REP

| Mate | of Inspection : \ | 1 12 2 20 | The state of the s |
|--|---|--|--|
| Divis | ion: | District. | |
| Name | e of the Road: | Tangua Cham | saran |
| Scher | ne/Programmo | MADE TO COM | 1 |
| LACKS | ge No.: | New Marit | |
| Status | of the Project: | Ongoing (C. Road Id No.: Q. 170 Color | Policy) |
| Work is a case of: | | Ongoing/Completed/Under Maintenance New Connectivity/I | |
| SI. No | | ottyfty/Op gradation/ Mainte | |
| 1. | 1 | Parameters to be checked | 1 |
| direction of the last of the l | Payement | | Remarks |
| a) | Road Junction condition | | |
| b) | Condition of Surfacing | | |
| c) | Riding Quality | | S/U |
| d) | Road Camber | | S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement | | S/U |
| | OILOIL. | | d Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | | |
| 2. | Cross Drainag | | Yes/No |
| a) | | Control of the Contro | to get the same |
| - | Condition of head walls in Hume pipe culverts including its painting | | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts. | | S/SRI/U |
| c) | | lings/slab/approach for Bridges | S/SRI/I |
| | Road Forniture | | |
|) | Whether sign b stones/Pavement | poards/informatory/cautionary Board/km & 200 road markings are provided and maintained | Om Yes/N |
| | elompliance His | logy | n single constraints |
| S | Status of ATR's | & any others | |
| | | | |

Overall Rating

N.A

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

Note Work not started

NAME: Ranchordre Passen DESIGNATION: Grentone Engineer

11/12/2020

(Signature)

Executive Engineer
R.W.D. (W) Division
Dhaka