## FIELD INSPECTION REPORT

TILLD HAST ECTION REPORT			
		District: Samastipur	
Division: RWD Dalsinghsarai Length(km): 2.05216		~	
Name of Road: MDR to Shakhara			
Scheme / Programme: MAINTENANCE HEW MR 2018			
Package No: Road Id No:			
Status of the Project: Ongoing/Completed/Under Maintenance _ Tender fresels = Work is a case of: New Connectivity/ Up gradation/ Maintenance - up gradation/			
SI. No	Parameters to be Checked		Rema Iss
1	Pavement		
a)	Road Junction Condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		
f)	Constraction Joint provided or not(CC Pavement)		
ဋ)	Compaction of flank/slope & raincuts if any		
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridge		
3	Road Furniture		
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		-
4	Compliance History		
a)	Status of ATR's & any others		Mo
	Tender Prosses. I'm this food Hence Grade not owarder.  Overall Rating:		
	Satisfactory(S)		1801, W.Y
	Satisfactory but requires Improvement(SRI)		
	Unsatisfactory(U)		

(Signa, 10)

NAME: Amil Presed
DESIGNATION: 72