


# FIELD INSPECTION REPORT

| Date of Inspection: 14.12.2020  |  | District: Samastipur                                       |
|---|--|--|
| Division: RWD Dalsinghsarai   |  | Length(km): 1.590 km                                       |
| Name of Road : NH to Bhagwatpur   |  |  |
| Scheme / Programme: MAINTENANCE   |  | New MP 2018  |
| Package No:   |  | Road Id No:  |
| Status of the Project: Ongoing/Completed/Under Maintenance - on Tender process. |  |  |
| Work is a case of:  |  | New Connectivity/ Up gradation/ Maintenance - up gradation |
| Sl. No  | Parameters to be Checked   | Remarks  |
| 1   | <b>Pavement</b>  |  |
| a)  | Road Junction Condition  |  |
| b)  | Condition of Surfacing   |  |
| c)  | Riding Quality   |  |
| d)  | Road Camber  |  |
| e)  | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement                          |  |
| f)  | Constraction Joint provided or not(CC Pavement)  |  |
| g)  | Compaction of flank/slope & raincuts if any  |  |
| 2   | <b>Cross Drainage</b>  |  |
| a)  | Condition of head walls in Hume pipe culverts including its painting   |  |
| b)  | Condition of Abutment & Wing walls , Slab in RCC culverts  |  |
| c)  | Condition of railings/slab/approach for Bridge   |  |
| 3   | <b>Road Furniture</b>  |  |
| a)  | Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained |  |
| 4   | <b>Compliance History</b>  |  |
| a)  | Status of ATR's & any others   | NO   |

Tender process in this road. Hence Grade not awarded

Overall Rating :

|  |     |
|--|-----|
| Satisfactory(S)                            | N/A |
| Satisfactory but requires Improvement(SRI) |     |
| Unsatisfactory(U)                          |     |

  
 (Signature)

NAME:

DESIGNATION :

And present  
 JS