FIELD INSPECTION REPORT

	TIEED HADT ECTION REIN	
Date of Inspection: 14.12. 2020 District: Samastipur		
Division: RWD Dalsinghsarai Length(km): 2.450km		
		School to Harrian vola
_	eme/Programme: MAINTENANCE on Tender prosses	Hew sgrowsonson
Package No: Road Id No: MR 2018 Metter		
Stat	tus of the Project: Ongoing/Completed/Under Maintenance . 9n Te	ndr prosses:
<u> </u>	rk is a case of: New Connectivity/ Up gradation/ Maintenance	up gradation.
SI. No	Parameters to be Checked	Rema les
1	Pavement	
a)	Road Junction Condition	
b)	Condition of Surfacing	-
c)	Riding Quality	_
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	_
f)	Construction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	Compliance History	
a)	Status of ATR's & any others	40
	Road is in Tender Process. He Overall Rating:	enes Goode not oma sold
	Satisfactory(S)	M.A.
	Satisfactory but requires Improvement(SRI)	
	Unsatisfactory(U)	The state of the s

מסכני[אין אינו)

NAME: JO