

FIELD INSPECTION REPORT


Date of Inspection: 13.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 1.4 km
Name of Road : Dharmik Lal Chowk to Balbhadra (Purga Sthan)		
Scheme / Programme: MAINTENANCE MR / old		
Package No:		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance Beyond Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance

Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	Work completed on 13/02/2013 No provision of 5 year Maint -
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Constriction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

- N/A -

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	


 12/12/20
 (Signature)

NAME: **Manoj Kumar**
 DESIGNATION: **AE**