

FIELD INSPECTION REPORT

Date of Inspection:	13.12.2020	District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 0.800 km
Name of Road :	Riti Raj Singh house to Pathmic Sanskrit Vidyalyay Tinwari/49.	
Scheme / Programme:	MAINTENANCE	MR 201
Package No:		Road Id No:
Status of the Project:	Ongoing/Completed/Under Maintenance	Beyond Maintenance
Work is a case of:	New Connectivity/ Up gradation/ Maintenance	

Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	Work Completed on 29/03/13 There was no provision of 5 year Maint. DPR Section in HR Policy doc.
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

- N.A. -

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

[Signature]
13.12.2020

Ramesh Kumar Singh

(Signature)

NAME:

DESIGNATION :