

FIELD INSPECTION REPORT


Date of Inspection: 12.12.2020		District: Samastipur	
Division: RWD Dalsinghsarai		Length(km): 3.57	
Name of Road: Kalyanpur Mahabir Manohar to Mahisari via Chakhabari			
Scheme / Programme: MAINTENANCE MR abt			
Package No:		Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance Beyond Maintenance			
Work is a case of:		New Connectivity/ Up gradation/ Maintenance	

Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	Work completed on 24/11/14 there was no provision of 5 years Maint. DPR Sent to New MR Policy
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

- NA -

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	


 12.12.2020
 (Signature)

Ramesh Kumar Singh
 i/r

NAME:
DESIGNATION :