

FIELD INSPECTION REPORT

Date of Inspection:	14.12.2020	District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 5.0
Name of Road :	Dadu chowk to Kapsan chowk	
Scheme / Programme:	MAINTENANCE	M/R old
Package No:		Road Id No:
Status of the Project:	Ongoing/Completed/Under Maintenance Beyond Maint.	
Work is a case of:	New Connectivity/ Up gradation/ Maintenance	
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	
b)	Condition of Surfacing	Work sanctioned under New M/R 2018. Work in progress
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

- N.A -

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

14/12/20
(Signature)

NAME: Manoj Kumar
DESIGNATION: AE