

FIELD INSPECTION REPORT

Date of Inspection: 0-12-2020	District: Begusarai
Division: Muzaffarpur	Length (km): 4.852 Km
Name of the Road: Repair of Road for Canal pass to Malipura PWD 2020	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 32010808019
Status of the Project: Ongoing/Completed/Under Maintenance	out of Maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	out of Maintenance
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

S. M. Aminul Haque
(Signature) 21/12/2020

NAME: S. M. Aminul Haque

DESIGNATION: J.E