FIELD INSPECTION REPORT

Date of Inspection: 0	2-12-20	District: - Rolles
Division: RWDW do	vision sagaron-1	Length (km): 3-111
Name of the Road: &	savam class	roed to Bablas Barketa.
Scheme/Programme:	MAINTENANCE	
Package No.: MR-H 20	19-20, Salabam-11 07	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

SI. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any	Yes/No	
	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
	Complisies History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

Alm

NAME: ASHUR Poosed Sinn

DESIGNATION: AG