

FIELD INSPECTION REPORT

Date of Inspection : 06.12.2020

District: MUZAFFARPUR

Division: MUZAFFARPUR EAST

Length (km):

Name of the Road: Repair of Road from Nawada Chauri to Kosi Binda NH-57 Subharpur, Roushniapur.

Scheme/Programme: MAINTENANCE

Package No.:

Road Id No.:

RC 0 Transferred

Status of the Project: Ongoing Completed Under Maintenance

Work is a case of: New Connectivity Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SA
b)	Condition of Surfacing	SA
c)	Riding Quality	SA
d)	Road Camber	SA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)


(Signature)

NAME:

DESIGNATION: