

MR (3054)

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020	District: Sitamarhi
Division : BELSUND	Length (km): 0.900 KM
Name of the Road: NH 77 Thana Chok to Runnisaipur DAY school	
Scheme/Programme: MAINTENANCE	MR (3054)
Package No.: MBD 01/2017-18	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	(Ind year)
Work is a case of: New Connectivity/Lip gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SAT (S)
b)	Condition of Surfacing	SAT (U)
c)	Riding Quality	SAT (U)
d)	Road Camber	SAT (S)
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NO
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage NA	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NO
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI ✓
Unsatisfactory (U)	

(Signature)

NAME: SURENDRA KUMAR SINGH
DESIGNATION: SE