FIELD INCOME.				
Date of Inspection: 08-12-20 District : East Champers				
Division : Chakia District : East Champaran				
Name of the Book and the Control Length (Km): 5.838 k				cny
Schame (Dur Clarker Victoria) Vishamba achus Roumbas Clarkert al				
Package No.:				
Status of the Dusing A				
Work is a case of :		Ongoing/Completed/Under Maintenance		
SI. No. Parameters to be chec		New Connectivity/Up Gradation/ Maintenance		
1,	Pavement Remarks			
a)	Road Junction condition			- NA -
b)	Condition of Surfacing			- NA-
c)	Riding Quality			- NA-
d)	Road Camber			- NA-
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			-
f)	Contraction Joints provided or not (CC Pavement)			-
g)	Compaction of flank/slope & raincuts if any			
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			- NA -
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts			
c)	Condition of railings/slab/approach for Bridges			
3,	Road Furniture			
a)	Road Furniture Whether sign board/informatory/cautionary Board/Km & 200m - NA- Stones/Pavement road markings are provided and maintained			
4,	Compliance History			_
a)	Status of ATR's & any	y others		
	Overall Rating : Satisfactory (S) Satisfactory but requires improvement (SRI) Unsatisfactory (U)			-
ţ	Unsatisfactory (U) PM MJ7 Phone-II (DRRP). (Signature)			

NAME:

DESIGNATION: