Transfer to pw D

FIELD INSPECTION REPORT

old me

Date of l	inspection : \	312-20	District: Rokled	
Division	· Awalwadi	HARDER MININ	Length (km): 8.10/41/	-
Name of	the Road:	सावामा जाका पुत्र ह	34348(4)	-
Scheme/	Programme:	MAINTENANCE 1		
Package	The second secon		Road Id No.:	
S. 1.100 (100 (100 (100 (100 (100 (100 (1	f the Project:	Ongoing/Completed/	projetion/ Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance Parameters to be checked		Remarks
1.	Pavement		The state of the state of	
a)	Road Junction condition		S/U	
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No	
n	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2	Great Drain	ige.	The Man Parist of Street	
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3.	Road Furnis	are		
a)	stones/Paven	ent road markings are	cautionary Board/km & 200m provided and maintained	Yes/No
4	Compliance	History	The Name	1
a)	Status of AT	R's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Asuk Proced Singy

DESIGNATION: