FIELD INSPECTION REPORT

District: Date of Inspection: 13-12-20 3:420140 Length (km): Division: Rw D/ w/ division, Sasatrom Pakan via sondika Name of the Road: Tendua To MAINTENANCE L Scheme/Programme: Package No.: MR-H 2019-20, Sasaron -1 19 Road Id No.: Ongoing/Completed/Under Maintenance Status of the Project: New Connectivity/Up gradation/ Maintenance Work is a case of:

SI. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	-7
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
	Compliance History	
a)	Status of ATR's & any others work with St	artad

Overall Rating

men Men

Mode Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

(Signature)

NAME: ASHAL Product Som

DESIGNATION: AC