

FIELD INSPECTION REPORT

Date of Inspection : 5/12/20		Division : Madhepura	District : Madhepura
Name of the Road : D. B. Road to Bahadur Singh Chakala		Length (km): 1.00 K.M	
Scheme/Programme : MAINTENANCE		Road Id No.: MR-3054 (old)	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance N/A	
Work is a case of:		New Connectivity/Up gradation/ Maintenance N/A	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	NA S/U	
b)	Condition of Surfacing	N/A S/U	
c)	Riding Quality	N/A S/U	
d)	Road Camber	N/A S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A	
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N/A	
4.	Compliance History		
a)	Status of ATR's & any others	-	

Overall Rating :

Satisfactory (S)	N/A
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Birendra Kumar
J.E. Madhepura

NAME:

Birendra
5/12/20
(Signature) J.E