

FIELD INSPECTION REPORT

Date of Inspection : 11.12.2020		District: East Champaran.
Division : R.W.D. (W) Dhaka.		Length (km): 7.10
Name of the Road: Fulwariya Ghat to Kundwa chainpur Road.		
Scheme/Programme: MAINTENANCE		F.D.R. 3054
Package No.:		Road Id No.: 31708600816
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Riding Quality	✓/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓/Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

NOTE:- Some Part of Road in 2nd KM & 3rd KM are damaged due to flood during Rain/ Flood in year 2020-21 & 2019-20. But road is Motarable.

[Signature]
11/12/2020
(Signature)

NAME: *Shekh Muvul Hossain*
DESIGNATION: A.E
[Signature]
11/12/2020
EE