

FIELD INSPECTION REPORT

Date of Inspection :	9/12/2020	District:	East Champaran.
Division :	R.W.D (W) Dhaka.	Length (km):	4.250
Name of the Road:	Ghandar 22 Mile to Madhaya Vithalaya Saphi		
Scheme/Programme:	MAINTENANCE	F.D.R. 3054	
Package No.:		Road Id No.:	3170800833
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		S/U
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No /
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		S/SR/U
a)	Condition of head walls in Hume pipe culverts including its painting		S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SR/U
c)	Condition of railings/slab/approach for Bridges		S/SR/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		N/A

Overall Rating :

Satisfactory (S)	S'
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

NAME:

Shakti Kumar Hooda

DESIGNATION:

A.E

(Signature)

9/12/2020