

FIELD INSPECTION REPORT

Date of Inspection : 12.12.2020		District: East Champaran
Division : R.W.D (W) Dhaka.		Length (km): 2.950
Name of the Road: Bhandar P.W.D Road to Padumker Siwan		
Scheme/Programme: MAINTENANCE F.D.R. 3054		
Package No.:		
Status of the Project:	Road Id No.: 3170860082	
Work is a case of:	Ongoing/Completed/Under Maintenance	
	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

NOTE:- Some Part of Road in 1st km & 3rd km are damaged due to flood during Heavy Rain/ Flood in year 2020-21. But road is Motorable.

Bhadrachari
12/12/2020
(Signature)

NAME: Sheshnath Hada.

DESIGNATION: A.E

EE
12/12/2020
EE