Date of I	nspection: 12.12.2020	
Division		
Vame of	K.W.D (W) Dhaka Length (low)	
	Chandanbara + D 2.00	
Package	rogramme: MAINTENANCE	
Statue of	Road Id No.	200 -
Work is	Ongoing/Completed/Under Maintenance	1817
Sl. No.	New Connectivity/Up gradation/ Maintenance	
	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	'S/U
c)	Riding Quality	'S/U
d)	Road Camber	\$/U
e) .	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b) .	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
(c)	Condition of railings/slab/approach for Bridges	S/SRI/U
STATE SHE THEODY	Road Furniture	· · · · · · · · · · · · · · · · · · ·
a)	Whether sign boards/informatory/cautionary Board/km & 200	m Yes/No
4.	Compliance History	NA
a)	Status of ATR's & any others	176

Overall Rating

	107
Satisfactory (S)	7
Satisfactory but requires Improvement (SRI)	-
Satisfactory but requires important	
Unsatisfactory (U)	

(Signature)

NAME: Shelch Nurultoda.

DESIGNATION: A-E

E.E.