FIELD INSPECTION REPORT

Date of 1	Inspection: \>	12 2020 Distr	ict: East Cham	harrin	
			1	parat)	
	the Road: Ri	The state of the s	th (km): 3.80 Km	Bhagway	
	Programme:	MAINTENANCE MI	3 3054	in region	
Package	No.:		Id No.: 317086	0080030	
Status of	the Project:	Ongoing/Completed/Under			
Work is	a case of:	New Connectivity/Up grad	ation/ Maintenarice		
Sl. No.	Signature of the second second second	Parameters to be che	cked	Remarks	
1.	Payement				
a)	Road Junction condition			√S/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			∨S/U	
d)	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
a)	Condition of Abutment & Wing walls, Slab in RCC culverts.			S/SRI/U	
b)	Condition of Abuunent & wing water, Sand			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges				
3.	Road Furniture			Yes/No	
a)	Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History			N·A	
a)	Status of ATR	's & any others	And American State of the State		
				'5'	
Sugrall F	Pating :	Satisfactory (S)	(CDI)	-	

Overall Rating

	'5'
Satisfactory (S)	
Satisfactory (S) Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	
Unsatisfactor	9

NAME: Ramboudre Parson

DESIGNATION: Exceptive Cypiner

Executive Engineer R.W.D. (phaka)